Name: Kildare County Council Date: 26/04/19

Address: Aras Chill Dara, Devoy Park

Naas, Co Kildare

Ref: Brooke Bridge

OCSC O'CONNOR | SUTTON | CRONIN Multidisciplinary Consulting Engineers

HEAD OFFICE 9 Prussia Street

T | +353 (0)1 8682000 F | +353 (0)1 8682100

E | ocsc@ocsc.ie

W | www.ocsc.ie

Dublin 7

Ireland

RE: PRINCIPLE BRIDGE INSPECTION REPORT

- Bridge Road Surface
 New road surface required 30m x5m
- Expansion Joints No Issue
- Upstream Grass Verge No Issue
- Downstream Grass Verge No Issue
- Upstream Roadside Parapet
 De-vegetation of parapet and rake & repoint 10% of joints
 Section of wall to be reconstructed 8m x 0.35m x 0.45m
 Reset capping full length of parapet
- Downstream Roadside Parapet Section of wall to be reconstructed 15m x 0.8m x 0.35m Rake and repoint 40% of joints
- Upstream Riverside Parapet No issue
- Downstream Riverside Parapet
 Vegetation to be removed and parapet to be raked and repointed
 4m x 1.5m section to be reconstructed
- Downstream Right Embankment Retaining wall to be reconstructed
- Downstream Left Embankment
 A fence is required along the left embankment.
- Upstream Right Embankment No issue











 $Civil \,|\, Structural \,|\, Mechanical \,|\, Electrical \,|\, Sustainability \,|\, Environmental$

O'Connor Sutton Cronin & Associates Limited - Registered in Ireland No. 138329

Directors: Tony Horan (MD) | James Barrett (Secretary) | Paul Healy | Brian Madden | Martin McGrath | Francis McNulty | John Millar | Andrew O'Brien | Michael O'Reilly | Brian O'Rourke
Associate Directors: Anthony Horan | Paul McSteen

- Upstream Left Embankment No Issue
- Right Abutment No Issue
- Left Abutment No Issue
- Right Pier N/A
- Left Pier N/A
- Upstream to mid deck Bridge deck to be 100% repointed
- **Spandrel Walls** Vegetation to be removed and joints to be raked and repointed
- **Upstream Riverbed** No Issues
- Downstream Riverbed Scour protection has eroded away and requires a new scour protection.
- Upstream Left Embankment Car tyre to be removed Section of wall to be rebuilt Air Valve and Water main in embankment
- Instream Works Could not access river to due to the level of the water being too high.



HEAD OFFICE 9 Prussia Street Dublin 7 Ireland

T | +353 (0)1 8682000 F | +353 (0)1 8682100 E | ocsc@ocsc.ie W | www.ocsc.ie











Civil | Structural | Mechanical | Electrical | Sustainability | Environmental